

Inspection Photos
N. PARACHUTE-65S95W 31NWNW (D31)
Location # 335674
CAERUS PICEANCE LLC 10456



Location battery sign.



Wells

Inspection Photos
N. PARACHUTE-65S95W 31NWNW (D31)
Location # 335674
CAERUS PICEANCE LLC 10456



EF12B-DX API # 05-045-15486



Gas bubbling in cellar.

Inspection Photos
N. PARACHUTE-65S95W 31NWNW (D31)
Location # 335674
CAERUS PICEANCE LLC 10456



EF12C API # 05-045-14659



Gas bubbling in cellar.

Inspection Photos
N. PARACHUTE-65S95W 31NWNW (D31)
Location # 335674
CAERUS PICEANCE LLC 10456



Open hole behind gas meter sheds.