

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/24/2019

Submitted Date:

05/31/2019

Document Number:

680305011

FIELD INSPECTION FORM

Loc ID 415358 Inspector Name: SCHURE, KYM On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 66190
Name of Operator: OMIMEX PETROLEUM INC
Address: 7950 JOHN T WHITE ROAD
City: FORT WORTH State: TX Zip: 76120

Findings:

7 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Fisher, Jeremy	970-854-4733	Jeremy_Fisher@omimexgroup.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
280914	WELL	PR	07/29/2010	GW	125-09607	Bennett 4-15-5-45	PR

General Comment:

[Routine Site Inspection](#)

Location			
Lease Road:			
Type	Access		
comment:	Located within irrigated cropland w/seasonal access		
Corrective Action:			Date:
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:	Satisfactory		
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	Satisfactory		
Corrective Action:			Date: _____
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	WELLHEAD		
Comment:	FGW		
Corrective Action:			Date:
Equipment:			
Type: Gas Meter Run	# 1		corrective date
Comment:			
Corrective Action:			Date:
Type: Vertical Separator	# 1		
Comment:			
Corrective Action:			Date:
Venting:			
Yes/No			
Comment:			
Corrective Action:			Date:
Flaring:			
Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities

Facility ID: 280914 Type: WELL API Number: 125-09607 Status: PR Insp. Status: PR

Producing Well

Comment: [FGW](#)

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	In Process	Other	In Process			

Comment: [Located within irrigated rotational cropland w/rotational tillage](#)

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT