

Operator Fritzler Resources, Inc.

Lease Location Project No. Scott Federal #1 Washington

Remediation Project: 9400

Project No.		9400									Bck 2 * Bck		4 or 2 X background	
Remediation Project:														
Description	Sample ID	Sample Date	Depth	Benzene mg/Kg	Toluene mg/Kg	Ethybenzene mg/Kg	Xylene mg/Kg	DRO(TEPH) mg/Kg	GRO(TVPH) mg/Kg	HEM mg/Kg	SAR	pH	Conductance mS/cm	
Table 910-1 Levels				0.17	85	100	175	500			12			
Skim Pit	East SK FD Pit	9/4/2013						149				7.19	0.892	
Windrows	Sctf-1-E1	9/12/2017	composite					514	<0.5	3789	2.6		3054	
	SCTF-2-M	9/12/2017	composite					605	<0.5	4237	2.9		2119	
	SCTF-3-W1	9/12/2017	composite					<10	<0.5	<50	4.3		2805	
	SCTF-4-5	9/12/2017	composite					3202	4.02	7783	8.4		450	
Average								1080.25	1.005	3952.25	4.55		2107	
Skim Pit														
	Excavated wall sample	N	3/28/2019	3 ft	<0.01	<0.01	<0.01	<0.01	32.1	0.87	10.6	8.37	1.232	
	Excavated wall sample	E	3/28/2019	3 ft	<0.01	<0.01	<0.01	<0.01	39.8	<0.5	4.4	7.95	0.621	
	Excavated wall sample	W	3/28/2019	3 ft	<0.01	<0.01	<0.01	<0.01	14.9	0.56	1.9	8.53	0.483	
	Excavated wall sample	S	3/28/2019	3 ft	<0.01	<0.01	<0.01	<0.01	1265	16.5	11.9	8.32	0.757	
The east, south , and west walls were further excavated.														
Skim Pit														
	Excavated wall sample	SF SKM N	4/16/2019	3 ft	<0.01	<0.01	<0.01	<0.01	32	<0.5				
	Excavated wall sample	SF SKM W	4/16/2019	3 ft	<0.01	<0.01	<0.01	0.03	<10.0	<0.5				
	Excavated wall sample	SF SKM S	4/16/2019	3 ft	<0.01	<0.01	<0.01	<0.01	<10.0	<0.5				
	Excavated wall sample	SF SKM E	4/16/2019	3 ft	<0.01	<0.01	<0.01	<0.01	<10.0	<0.5				
	Excavated wall sample	SF SKM B	4/16/2019	8 ft.	<0.01	<0.01	<0.01	<0.01	71.2	<0.5				
Land Farm Area														
	3 foot composite samples	SCT FD SW	4/16/2019	3 foot composite	<0.01	<0.01	<0.01	0.01	15.7	<0.5	1.8	7.15	692	
	3 foot composite samples	SCT FD SE	4/16/2019	3 foot composite	<0.01	0.01	<0.01	0.02	<10.00	<.5	1.1	7.56	478	
	3 foot composite samples	SCT FD NE	4/16/2019	3 foot composite	<0.01	<0.01	<0.01	<0.01	80.2	<.5	2.1	7.44	472	
	3 foot composite samples	SCT FD NE	4/16/2019	3 foot composite	<0.01	<0.01	<0.01	<0.01	36.8	<.5	1.5	7.49	745	
	3 foot composite samples	SCT FD C	4/16/2019	3 foot composite	<0.01	<0.01	<0.01	<0.01	27.1	<.5	2.2	7.34	492	
Perimeter Analysis around skim pit														
	3 foot composite samples	SF Per.W	4/16/2019	3 foot composite							4.5	7.23	589	
	3 foot composite samples	SF Per.N	4/16/2019	3 foot composite							4.6	7.23	511	
	3 foot composite samples	SF Per.S	4/16/2019	3 foot composite							3.8	7.32	504	
	3 foot composite samples	SF Per.E	4/16/2019	3 foot composite							5.2	7.28	508	