

Inspection Photos
Location Name: Elaine 43-28
Location ID: 336320



Pic 1 unpainted tank, uncapped lines on tank



Pic 2

Inspection Photos
Location Name: Elaine 43-28
Location ID: 336320



Pic 3 unpainted tank, uncapped line



Pic 4