

Smith Energy LLC, Maggard 2-11  
121-09567

Inspection #688304717

5/29/2019

Routine Inspection



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources



Colorado Oil and Gas Conservation Commission  
39.89284, -102.94116, 4383.2ft, 341°  
05/29/2019 12:00:41 PM





Colorado Oil and Gas Conservation Commission  
39.89256, -102.94117, 4386.5ft, 347°  
05/29/2019 11:59:35 AM





Colorado Oil and Gas Conservation Commission  
39.89258, -102.94119, 4393.0ft, 38°  
05/29/2019 11:59:41 AM




Colorado Oil and Gas Conservation Commission  
39.89283, -102.94117, 4383.2ft, 142°  
05/29/2019 12:01:33 PM





Colorado Oil and Gas Conservation Commission  
39.89256, -102.94128, 4379.9ft, 293°  
05/29/2019 11:59:57 AM





Good interim  
reclamation.

Colorado Oil and Gas Conservation Commission  
39.8926, -102.94129, 4383.2ft, 3°  
05/29/2019 12:00:13 PM