

Inspection Photos
Location Name: SINJIN-66N65W /36SWSW
Location #: 328688



Photo #1

Sinjin E 36-13 (API # 05-123-16306) Wellsite

Temporarily Abandoned | TA

No LOTO on Master / Casing valves

No LTSI or Decommission TA/SI tags per agreement

Unused Equipment



Photo #2

Sinjin E 36-9, 11, 12, 13, 25, LDS F 1-29 Battery

Shut-down

Mud w/ puddles from prior rain