

Inspection Photos

Operator: Kinder Morgan
Location/API #: 033-06135
Date: 5-30-2019



Photo 1. View of the project area from the southeastern corner facing center.



Photo 2. View of the southern portion of the project area from the southwestern corner facing westward.



Photo 3. View of stormwater controls in the southern project area facing southwestward.



Photo 4. View of the eastern project area from the southeastern corner facing northward.



Photo 5. View of reference area facing southward.