

Inspection Photos
Location Name: Nick Hager 12-22
Location ID: 305127



Photo 1: Wellhead



Photo 2: Location



Inspection Photos
Location Name: Nick Hager 12-22
Location ID: 305127



Photo 3: Centralized Tank Battery



Photo 4: No BBLS listed on Produced Water Tank



Inspection Photos
Location Name: Nick Hager 12-22
Location ID: 305127



Photo 5: Unused equipment



Photo 6: Unused tank



Inspection Photos
Location Name: Nick Hager 12-22
Location ID: 305127



Photo 7: Unused equipment (south of tank battery)



Photo 8: Unused equipment (south of tank battery)



Inspection Photos
Location Name: Nick Hager 12-22
Location ID: 305127



Photo 9: Unused equipment (SE of tank battery)