

Inspection Photos

Location Name: COCKROFT USX A-66N64W /11SENE

Location #: 333034



Photo #1

Cockcroft USX A 11-8 Wellsite

Temporarily Abandoned | TA

prior insp.



Photo #2

Cockcroft USX A 11-8 (05-123-24711) Wellsite

Temporarily Abandoned | TA

Unused Equipment



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: COCKROFT USX A-66N64W /11SENE

Location #: 333034



Photo #3

Cockroft USX A 11-8 Battery site

Shut-down

*Weeds
prior insp.*



Photo #4

Cockroft USX A 11-8 Battery Site

Abandoned – ALL equipment removed

*Weeds appear mitigated
Reclamation progressing*