

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/03/2019

Submitted Date:

06/03/2019

Document Number:

693500260**FIELD INSPECTION FORM**
 Loc ID 456747 Inspector Name: Silver, Randy On-Site Inspection ☐ 2A Doc Num: _____
Operator Information:OGCC Operator Number: 10459Name of Operator: EXTRACTION OIL & GAS INCAddress: 370 17TH STREET SUITE 5300City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:5 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Adamczyk, Megan		megan.adamczyk@state.co.us	
Carlisle, J	970-534-6006	COGCCInspections@extracti onog.com	ALL INSPECTIONS

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
456753	WELL	DG	03/27/2019		014-20773	Interchange B N35-20-9N	DG

General Comment:

LocationOverall Good: ☒**Signs/Marker:**

Type	DRILLING/RECOMP		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:		
Corrective Action:		Date: _____

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

Type	LOCATION		
Comment:	Sound walls		
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 456753 Type: WELL API Number: 014-20773 Status: DG Insp. Status: DG**Well Drilling**

Rig: Rig Name: Patterson 901 Pusher/Rig Manager: Danny Herrera
 Permit Posted: Yes Access Sign: Yes

Well Control Equipment:

Pipe Ram: _____ Blind Ram: _____ Hydril Type: _____
 Pressure Test BOP: Pass Test Pressure PSI: 5000 Safety Plan: YES

Drill Fluids**Management:**

Lined Pit: _____ Unlined Pit: _____ Closed Loop: YES Semi-Closed Loop: _____
 Multi-Well: YES Disposal Location: Waste Connections

Comment: Current depth at time of inspection was 11345ft. At time of inspection operator was starting to drill cellars for second row of wells.

Corrective Action: _____ Date: _____

COGCC Comments

Comment	User	Date
<u>Routine inspectio due to complaint. At time of inspection did not observe and unusual odors in or around location. Weather conditions: Clear and sunny.</u>	<u>silverr</u>	<u>06/03/2019</u>

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
<u>693500261</u>	<u>loc pic</u>	<u>http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4838921</u>