

**FORM  
INSP**Rev  
X/15

# State of Colorado

## Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/03/2019

Submitted Date:

06/03/2019

Document Number:

693500267

**FIELD INSPECTION FORM**

Loc ID 456747 Inspector Name: Silver, Randy On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_

**Operator Information:**

OGCC Operator Number: 10459

Name of Operator: EXTRACTION OIL &amp; GAS INC

Address: 370 17TH STREET SUITE 5300

City: DENVER State: CO Zip: 80202

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION  
☐ FOLLOW UP INSPECTION REQUIRED  
☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

3 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

| Contact Name    | Phone        | Email                                 | Comment         |
|-----------------|--------------|---------------------------------------|-----------------|
| Carlisle, J     | 970-534-6006 | COGCCInspections@extracti<br>onog.com | ALL INSPECTIONS |
| Adamczyk, Megan |              | megan.adamczyk@state.co.u<br>s        |                 |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name           | Insp Status |
|-------------|------|--------|-------------|------------|-----------|-------------------------|-------------|
| 456753      | WELL | DG     | 03/27/2019  |            | 014-20773 | Interchange B N35-20-9N | DG          |

**General Comment:**

**Inspected Facilities**

Facility ID: 456753 Type: WELL API Number: 014-20773 Status: DG Insp. Status: DG

**Complaint**

Comment: Inspection in response to complaint.  
 Field Inspector Assigned: Randy Silver  
 Complaint Received  
 Date: 06-02-2019  
 Complaint Contacted:  
 Date: 06-03-2019 Time: 2:18PM via email  
 Facility ID #: 456747  
 Inspection Document # 693500260  
 Complaint Document #200447366  
 Nature of Complaint: odor  
 Field Inspector Actions:  
 On 06-03-2019, I Field Inspector, Randy Silver was issued a complaint received by COGCC staff in reference to Odor. The complainant Mark Kadlecek 1171 W 149th Ave Broomfield CO stated the issues were occurring outside of his home.  
 On 06-03-2019, I attempted to make contact with the complainant via email on 6-03-19 at approx... 2:18PM. He indicated per his complaint that on 06-02-19-19 nasty odor that is mix of some sort of odorant and diesel fuel.  
 I performed a complete site inspection of the oil and gas location and associated wells in the area. At time of inspection, I did not smell any unusual odors. I spoke with Broomfield inspectors and they are aware of complaint and have responded to it.  
 At time of inspection, I spoke with Extraction drilling supervisor he stated at approx... time of complaint they were performing normal drilling operations, no unusual activity was taking place.  
 Weather conditions: Clear and sunny  
 See inspection document #693500260 per my inspection.  
 No violation of COGCC rules were observed at the time of the inspection.  
 All information reviewed and site inspection information were submitted to the COGCC for further review.

Corrective Action:

Date:

**COGCC Comments**

| Comment                                | User    | Date       |
|--|---------|------------|
| See Doc#693500260 for full inspections | silverr | 06/03/2019 |