

# Inspection Photos

GR 23-11V Location Id. # 323872  
TEP ROCKY MOUNTAIN LLC



**No well sign.**



**No battery sign.**

# Inspection Photos

## GR 23-11V Location Id. # 323872

### TEP ROCKY MOUNTAIN LLC



Well and battery signs behind separators.



Well and battery signs behind separators.





**Inspection Photos**  
**GR 23-11V Location Id. # 323872**  
**TEP ROCKY MOUNTAIN LLC**



**No label on tank.**



**No label on tank.**

**Inspection Photos**  
**GR 23-11V Location Id. # 323872**  
**TEP ROCKY MOUNTAIN LLC**



**No label on tank.**



**No label on tank.**