

Inspection Photos

Location Name: Cuttings Area UWF H04 596

Location ID: #433573

Inspection Date: May 30, 2019



Photo #1 – Overview of location from west.



**Photo #2 – Overview of location from northeast. Note
downed sign on right side of photo.**



Inspection Photos

Location Name: Cuttings Area UWF H04 596

Location ID: #433573

Inspection Date: May 30, 2019



Photo #3 – Cuttings advisory sign was down on inspection date.



Photo #4 – Stormwater accumulation on top of cuttings pile. Note: it was raining during field inspection.



Inspection Photos

Location Name: Cuttings Area UWF H04 596

Location ID: #433573

Inspection Date: May 30, 2019



Photo #5 – Stormwater accumulation and trash on top of west cuttings pile.



Photo #6 – Stormwater accumulation and PVC debris on top of west cuttings pile.

