



### Certificate of Pipeline Inspection

In accordance with COGCC Rule 1102.h, this Certificate of Pipeline Inspection is to be completed by a third-party pipeline inspector prior to the pipeline named below being placed into service. By the execution of this Certificate, the pipeline inspector is certifying that the pipeline named below was installed as prescribed by the manufacturer's specifications, in accordance with Noble Midstream's Construction Specifications, and in accordance with Colorado Oil and Gas Conservation Commission 1100 Series Rules, and that the certifying inspector has provided Noble Midstream with (i) all inspection records relating to the pipeline and (ii) copies of the inspector's training qualifications.

AFE/PROJECT NAME: 5000 268 Mustang IDP Phase II DP 409

IDP: ☒ Mustang ☐ East Pony ☐ Wells Ranch ☐ Black Diamond ☐ Greeley Crescent

PIPELINE NAME: DP 409 6" Produced Water

NOMINAL O.D. DIAMETER (in): 6" LENGTH (ft): 1943'

MATERIAL: ☐ Steel ☐ HDPE ☒ Flex Steel

TYPE: ☐ Crude Oil ☒ Produced Water ☐ Natural Gas

LOCATION/COUNTY: PL-0903 to PR-0903 / Weld

ROUTE DESCRIPTION: PL-0903 409 Pad to PR-0903 409 Junction

I, James Allison hereby certify that the DP 409 pipeline and all appurtenances were constructed and installed in accordance with all component manufacturing specifications, in accordance with Noble Midstream's Construction Specifications, and in accordance with Colorado Oil and Gas Conservation Commission 1100 Series Rules.

#### CHIEF INSPECTOR

NAME: James Allison

SIGNATURE: James Allison

COMPANY: NIDLI

EMAIL AND CONTACT NUMBER: Jimmy.Allison19@gmail.com

DATE: 4/19/19

#### NOBLE MIDSTREAM CONSTRUCTION SUPERVISOR or CONSTRUCTION MANAGER

NAME: Rogon Luce

SIGNATURE: Rogon Luce

DATE: 4/19/19