

## Inspection Photos

Location Name: PONY EXPRESS 44-31 & TR

API#: 05-071-07472 & 08545

INSP #: 695100787



**PHOTO 1: V WELLHEAD**



**PHOTO 2: TR WELLHEAD**

Inspection Photos  
Location Name: PONY EXPRESS 44-31 & TR  
API#: 05-071-07472 & 08545  
INSP #: 695100787



**PHOTO 3: WELL SIGNS**

**PHOTO 4: PRODUCED WATER IS ABOVE FREEBOARD. SPOKE WITH JACK WISEMAN AND HE SAID HE WILL CALL WATER TRUCK ASAP. Lower fluid level so at least two feet of freeboard exists per Rule 902.b. CA DATE 6/5/19.**