

Location

Overall Good:

Signs/Marker:

| | | | |
|--------------------|---|-------|------------|
| Type | OTHER | | |
| Comment: | PHOTO 3: WELL SIGNS/ CURRENT OPERATOR IS NOT POST ON WELL SIGN. | | |
| Corrective Action: | COMPLY WITH 210 SERIES RULES. | Date: | 08/04/2019 |

Emergency Contact Number:

| | | | |
|--------------------|----------------------|--|----------------------------|
| Comment: | <input type="text"/> | | |
| Corrective Action: | <input type="text"/> | | Date: <input type="text"/> |

Good Housekeeping:

| | | | |
|--------------------|---|-------|------------|
| Type | TRASH | | |
| Comment: | PHOTO 5: TRASH INSIDE ENGINE HOUSE. (WAS NOT NOTED ON PREVIOUS INSPECTION). PHOTO 6: TRASH INSIDE ENGINE HOUSE. (WAS NOT NOTED ON PREVIOUS INSPECTION). PHOTO 7: TRASH ON NORTH SIDE OF ENGINE HOUSE. (WAS NOT NOTED ON PREVIOUS INSPECTION). | | |
| Corrective Action: | REMOVE ALL TRASH AND DEBREE. COMPLY WITH RULE 603.f. | Date: | 07/04/2019 |
| Type | TRASH | | |
| Comment: | PHOTO 4: TRASH SHOWN IN PHOTO 3: OF INSP. DOC# 691401803 ORIGINAL CA DATE 2/8/19 HAS NOT BEEN REMOVED. (TRASH SHOWN IN PHOTO 4 OF PREVIOUS INSPECTION IS NO LONGER ON LOCATION). COMPLY WITH RULE 603.f. CA DATE IMMEDIATELY. | | |
| Corrective Action: | COMPLY WITH RULE 603.f. CA DATE IMMEDIATELY. | Date: | 06/04/2019 |

Overall Good:

Spills:

| Type | Area | Volume | | |
|------|------|--------|--|--|
| | | | | |

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:

| | | | |
|--------------------|----------------------|--|----------------------------|
| Yes/No | NO | | |
| Comment: | <input type="text"/> | | |
| Corrective Action: | <input type="text"/> | | Date: <input type="text"/> |

Flaring:

| | | | |
|--------------------|----------------------|--|----------------------------|
| Type | <input type="text"/> | | |
| Comment: | <input type="text"/> | | |
| Corrective Action: | <input type="text"/> | | Date: <input type="text"/> |

Inspected Facilities

Facility ID: 217288 Type: WELL API Number: 071-06064 Status: PR Insp. Status: PR

Producing Well

Comment:

Corrective Action:

Date:

Facility ID: 259761 Type: WELL API Number: 071-07274 Status: SI Insp. Status: SI

Producing Well

Comment:

Corrective Action:

Date:

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|-----------------|---|
| 695100790 | LOCATION PHOTOS | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4840652 |