

**Inspection Photos**  
**Location Name: UPRC Federal 23-1**  
**Location ID: 330502**



**Photo 1 – Old Tank Battery Sign from previous inspection**



**Photo 2 – Tank Battery sign has been updated to reflect the current operator**

**Inspection Photos**  
**Location Name: UPRC Federal 23-1**  
**Location ID: 330502**



**Photo 3 – Tank Battery**



**Photo 4 – Pumping Unit**

Inspection Photos  
Location Name: UPRC Federal 23-1  
Location ID: 330502



Photo 5 – Trash in Heater Treater house from previous inspection Doc ID 679600271



Photo 6 – Trash has been removed

**Inspection Photos**  
**Location Name: UPRC Federal 23-1**  
**Location ID: 330502**



**Photo 7 –Pit**