

Inspection Photos

Loc#419380

Operator: Ursa

Inspection Number: 692401043

Inspection Date: 5/30/19



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#1:
Overview of Location to Southeast.

May 30, ,2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Ursa Diemoz A Pad Loc#419380



Photo#2:
Vegetation on North Cut Slope is weedy on the upper portion, with Cheat grass, Mustard, and Filaree.

May 30, ,2019



Photo#3:
Vegetation on North Cut Slope is weedy on the upper portion, with Cheat grass, Mustard, and Filaree.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Ursa Diemoz A Pad Loc#419380



Photo#4:
Russian olive and knapweed on Location.



Photo#5:
Knapweed established outside Location perimeter.

May 30, ,2019



Photo#6:

Vegetation on South fill slope is commensurate with surrounding reference area hayfields.

May 30, ,2019



Photo#7:

Vegetation on West fill slope is commensurate with surrounding reference area hayfields.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Ursa Diemoz A Pad Loc#419380



Photo#8:
BMPs need maintenance at Southeast corner of site.

May 30, ,2019



Photo#9:
BMPs need maintenance at Southeast corner of site.



Photo#10:
Topsoil stockpiled south of entry.

May 30, ,2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Ursa Diemoz A Pad Loc#419380



Photo#11:
Views of topsoil stockpile from South side.