

Inspection Photos
Location Name: Bfarm pad
Location ID: 452914



Photo 1 sediment being carried onto HWY 7

Photo 2 sediment being carried on HWY 7

Inspection Photos
Location Name: Bfarm pad
Location ID: 452914



Photo 3 sediment being carried onto HWY 7

Photo 4 sediment being carried on HWY 7

Inspection Photos
Location Name: Bfarm pad
Location ID: 452914



Photo 5 sediment being carried onto HWY 7

Photo 6 sediment being carried on HWY 7

Inspection Photos
Location Name: Bfarm pad
Location ID: 452914



Photo 7 Tracking pad from HWY 7 into location



Photo 8 No BMP's in place around sediment dumped on side of road from street sweeper.