

# Inspection Photos

06/04/2019

Operator: FOUNDATION ENERGY  
MANAGEMENT LLC - 10112

Location ID: 331849

Inspection Doc. Number: 696200157  
Weld County, CO

Aaron Trujillo  
NE Reclamation Specialist  
COGCC

## Inspection Photos

Operator Name: FOUNDATION ENERGY MANAGEMENT LLC - 10112

Location ID: 331849



**Photo 1:** Photo taken from well location, facing north. Photo shows location remains predominantly bare and exposed soil. Unable to find evidence that additional reclamation has been conducted at the well site.



**Photo 2:** Photo taken from well location, facing west. Photo shows access road has not been reclaimed.

## Inspection Photos

Operator Name: FOUNDATION ENERGY MANAGEMENT LLC - 10112

Location ID: 331849



**Photo 3:** Photo taken from well location, facing west. Photo shows the access road “turn-around”. Photo shows access road has not been reclaimed.



**Photo 4:** Photo taken from well location, facing west. Photo shows the access road “turn-around”. Photo shows access road has not been reclaimed.

## Inspection Photos

Operator Name: FOUNDATION ENERGY MANAGEMENT LLC - 10112

Location ID: 331849



**Photo 5:** Photo taken from well location. Photo shows areas where Diffuse Knapweed is maturing and remains established on the location.



**Photo 6:** Photo taken from well location. Photo shows areas where Diffuse Knapweed is maturing and remains established along the access road.

## Inspection Photos

Operator Name: FOUNDATION ENERGY MANAGEMENT LLC - 10112

Location ID: 331849



**Photo 7:** Photo taken from the access road entrance, facing east. Photo shows cattle guard remains. Photo also shows access road has not been reclaimed in accordance with COGCC 1000 series reclamation rules.