

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/04/2019

Submitted Date:

06/05/2019

Document Number:

680305046**FIELD INSPECTION FORM**Loc ID 313696 Inspector Name: SCHURE, KYM On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10657Name of Operator: PCR OPERATING LLCAddress: 4040 BROADWAY STREET #510City: SAN ANTONIO State: TX Zip: 78209**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:9 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Wehrer, Gene	(970) 380-4860	gwehrer@passcreekresource s.com	Adena Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
224887	WELL	SI	11/01/2015	GW	087-05280	AJU JOHNSON-GLN 1	SI

General Comment:[Routine Site Inspection FIR](#)

Location

Lease Road:			
Type	Access		
comment:	Two track grassland		
Corrective Action		Date:	

Overall Good: ☐

Signs/Marker:			
Type	WELLHEAD		
Comment:	Satisfactory		
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:	Satisfactory		
Corrective Action:		Date:	

Overall Good: ☐

Spills:					
Type	Area	Volume			

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	Pipe		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Other	# 0		
Comment:	No surface/production equipment on well-site @ date of this FIR.		
Corrective Action:		Date:	

Venting:			
Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities									
Facility ID:	224887	Type:	WELL	API Number:	087-05280	Status:	SI	Insp. Status:	SI
Idle Well									
Purpose: <input checked="" type="checkbox"/> Shut In <input type="checkbox"/> Temporarily Abandoned Reminder: _____									
Comment: <input type="text" value="Routine Site Inspection"/>									
Corrective Action: <input type="text"/> Date: _____									

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	In Process	Other	In Process			

Comment:

Corrective Action:

Date:

Pits: ☐ NO SURFACE INDICATION OF PIT