

Inspection Photos

API: 05-099-06210

Operator: BERRY ENERGY INC

Inspection Date: 6/4/2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos



Photo 1. Standing at the location facing south toward the access road that has not been reclaimed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-099-06210 | Date: 6/4/2019

Inspection Photos



Photo 2. Facing north toward the location. Gravel remains and the location is not reclaimed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-099-06210 | Date: 6/4/2019

Inspection Photos



Photo 3. The surrounding reference area is wetland.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-099-06210 | Date: 6/4/2019