

Inspection Photos

API: 05-017-07385

Operator: CITATION OIL & GAS

Inspection Date: 6/4/2019



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 05-017-07385 | Date: 6/4/2019

Inspection Photos



Photo 1. A pipe riser remains at the location. Interfering with farming operations.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-017-07385 | Date: 6/4/2019

Inspection Photos



Photo 2. Close up view of pipe riser.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-017-07385 | Date: 6/4/2019