

# Inspection Photos

API: 05-017-07286

Operator: CITATION OIL & GAS

Inspection Date: 6/4/2019



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-017-07286 | Date: 6/4/2019

## Inspection Photos



**Photo 1.** A pipe riser remains at the location. Interfering with farming operations.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-017-07286 | Date: 6/4/2019

## Inspection Photos



**Photo 2.** A pipe riser remains at the location. Interfering with farming operations.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-017-07286 | Date: 6/4/2019