

Inspection Photos
Location Name: HSR-Croissant Battery
Location ID: 330730



Photo 1: Centralized Tank Battery



Photo 2: Erosion to north end of location

Inspection Photos
Location Name: HSR-Croissant Battery
Location ID: 330730



Photo 3: Erosion to north end of location (behind tank berm)