

Inspection Photos
Location Name: Fritzler/Hood/McGlothlin Battery
Location ID: 319142



Photo 1: Tank Battery Location.



Photo 2: Condensate Labeling NOT LEGIBLE



Inspection Photos
Location Name: Fritzler/Hood/McGlothlin Battery
Location ID: 319142



Photo 3: Condensate Labeling NOT LEGIBLE



Photo 4: Condensate Labeling NOT LEGIBLE



Inspection Photos
Location Name: Fritzler/Hood/McGlothlin Battery
Location ID: 319142



Photo 5: Condensate Labeling NOT LEGIBLE



Photo 6: Condensate Labeling NOT LEGIBLE



Inspection Photos
Location Name: Fritzler/Hood/McGlothlin Battery
Location ID: 319142



Photo 7: No labeling or NFPA placard



Photo 8: Berm in disrepair

Inspection Photos
Location Name: Fritzler/Hood/McGlothlin Battery
Location ID: 319142



Photo 9: Condensate Labeling NOT LEGIBLE



Photo 10: Condensate Labeling NOT LEGIBLE



Inspection Photos
Location Name: Fritzler/Hood/McGlothlin Battery
Location ID: 319142



Photo 11: Condensate Labeling NOT LEGIBLE



Photo 12: Condensate Labeling NOT LEGIBLE



Inspection Photos
Location Name: Fritzler/Hood/McGlothlin Battery
Location ID: 319142



Photo 13: Condensate Labeling NOT LEGIBLE



Photo 14: Condensate Labeling NOT LEGIBLE



Inspection Photos
Location Name: Fritzler/Hood/McGlothlin Battery
Location ID: 319142



Photo 15: Separator with trash.



Photo 16: Trash in separator.



Inspection Photos
Location Name: Fritzler/Hood/McGlothlin Battery
Location ID: 319142



Photo 17: Separator with trash



Photo 18: Trash in separator

Inspection Photos
Location Name: Fritzler/Hood/McGlothlin Battery
Location ID: 319142



Photo 19: Separator with stained soil



Photo 20: Stained soil



Inspection Photos
Location Name: Fritzler/Hood/McGlothlin Battery
Location ID: 319142



Photo 21: Separator that has stained soil



Photo 22: Stained soil



Inspection Photos

Location Name: Fritzler/Hood/McGlothlin Battery

Location ID: 319142



Photo 23: Cracked sight glass