

# Interim Reclamation Inspection

May 30, 2019

Operator: NOBLE ENERGY INC - #100322

Location ID: 425062

Inspection Document #: 697500177

Weld County, CO

NWNE Section 8 T4N R64W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**

Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Photos  
Location Name: RUFF C /08-27D  
Location ID: 425062



Aerial imagery taken in 2017. Aerial imagery shows an area around the well location and tank battery (red-dashed line). This area appears to have been disturbed during construction operations in 2011. Surface owner indicated the Operator disturbed portions of this area within the last 1-2 years and failed to perform reclamation activities. Surface owner attempted to get the Operator to perform reclamation but was unsuccessful. Surface owner decided to perform reclamation activities themselves which included this area and the adjacent area. Final land use change has occurred and the area is cropland, not rangeland.

Inspection Photos  
Location Name: RUFF C /08-27D  
Location ID: 425062



**Photo 1.** Photo taken from the southern tank battery location, facing West. Photo illustrates a crop field adjacent to the tank battery location. Operator will be responsible for complying with Reclamation rules within any historic and future disturbance associated with this tank battery and wells.



Inspection Photos  
Location Name: RUFF C /08-27D  
Location ID: 425062



**Photo 2.** Photo taken from the southern tank battery location, facing Southwest.  
See comments under Photo 1.

Inspection Photos  
Location Name: RUFF C /08-27D  
Location ID: 425062



**Photo 3.** Photo taken from the southern tank battery location, facing South. See comments under Photo 1.