

# Interim Reclamation Inspection

May 30, 2019

Operator: NOBLE ENERGY INC - #100322

Location ID: 330389

Inspection Document #: 697500180

Weld County, CO

SWNW Section 36 T5N R65W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

## Inspection Photos

Location Name: EHRlich STATE PC F /36-32D

Location ID: 330389



Aerial imagery taken in 2017. Aerial imagery shows a flowline area in which the Operator disturbed within the last 1-2 years and has failed to properly reclaim per Reclamation rules.

## Inspection Photos

Location Name: EHRlich STATE PC F /36-32D

Location ID: 330389



**Photo 1.** Photo taken from a portion of the flowline area, facing North. Photo illustrates a flowline area disturbance that has not been properly reclaimed per Reclamation rules. Photo illustrates bare ground with little, to no, establishment of reference area species.

Inspection Photos

Location Name: EHRLICH STATE PC F /36-32D

Location ID: 330389



**Photo 2.** Photo taken from a portion of the flowline area, facing East. See comments under Photo 1.

Inspection Photos

Location Name: EHRLICH STATE PC F /36-32D

Location ID: 330389



**Photo 3.** Photo taken from a portion of the flowline area, facing South. See comments under Photo 1.

Inspection Photos

Location Name: EHRLICH STATE PC F /36-32D

Location ID: 330389



**Photo 4.** Reference photo taken southeast from the flowline area, facing South. See comments under Photo 1.