

PADCO LLC, Fassler 6
121-09831
Inspection #688304791
6/6/2019
Routine Inspection



Colorado Oil and Gas Conservation Commission
40-10175, -103 32488, 4547-2ft, 7-
06/06/2019 07:57:14 AM



Colorado Oil and Gas Conservation Commission
40.10172, -103.3248, 4537.4ft, 2°
06/06/2019 07:57:33 AM



Colorado Oil and Gas Conservation Commission
40.10274, -103.32284, 4550.5ft, 171°
06/06/2019 08:02:52 AM



Colorado Oil and Gas Conservation Commission
40.10278, -103.32298, 4534.1ft, 125°
06/06/2019 08:02:32 AM



Colorado Oil and Gas Conservation Commission
40.10286, -103.32367, 4540.7ft, 103°
06/06/2019 08:00:30 AM



Colorado Oil and Gas Conservation Commission

40.10292, -103.3233, 4504.6ft, 97°

06/06/2019 08:03:48 AM



Colorado Oil and Gas Conservation Commission
40.10322, -103.32334, 4537.4ft, 75°
06/06/2019 08:04:10 AM