

# Inspection Photos

API: 05-061-06659

Operator: CITATION OIL & GAS

Inspection Date: 6/5/2019



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-061-06659 | Date: 6/5/2019

## Inspection Photos



**Photo 1.** Facing west along the former access road. Crop has not established in this area.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-061-06659 | Date: 6/5/2019

## Inspection Photos



**Photo 2.** Facing west toward the location. There are areas where the crop has not established.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-061-06659 | Date: 6/5/2019

## Inspection Photos



**Photo 4.** Facing toward the northwest side of location. Crop has not adequately established in this area.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-061-06659 | Date: 6/5/2019

## Inspection Photos



**Photo 5.** Facing southeast toward the location. Crop has not adequately established in this area.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-061-06659 | Date: 6/5/2019