

Final Reclamation Inspection

May 30, 2019

Operator: NOBLE ENERGY INC - #100322

Location ID: 309896

Inspection Document #: 697500185

Weld County, CO

NENE Section 16 T4N R64W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos

Location Name: RYANN STATE C #16-1

Location ID: 309896



Aerial imagery taken in 2017. Aerial imagery shows four areas circled in yellow. The southern tank battery circled in yellow serviced the three circled wells.

Inspection Photos

Location Name: RYANN STATE C #16-1

Location ID: 309896



Photo 1. Photo taken from the southern tank battery, facing South. Operator indicated this southern tank battery was decommissioned on 2/13/2019. Photo illustrates it has been over 3 months and not all equipment has been removed from location. Per Rule 1004, Operator shall make every reasonable effort to perform final reclamation before the next local growing season.