

Inspection Photos
Location Name: HSR-KNOX-65N67W /3NWSE
Location #: 332954



Photo #1
Shur View 23-3 (05-123-24195) Abandoned Battery site
Unused Equipment
Latrine, Pig Launcher
from prior insp.

Photo #2
Shur View 23-3 Abandoned Battery site
Unused Equipment
Latrine, Pig Launcher – Removed
Reclamation progressing