

Caerus Piceance LLC
API # 05-077-09240
Inspection # 696600093



Photo #1 Photo from entrance location

Caerus Piceance LLC
API # 05-077-09240
Inspection # 696600093



Photo #2 tank battery , one tank removed leaving rust stain inside containment.



Photo#3 @ wellheads on location one hooked up to rig for PA other is TA

Caerus Piceance LLC
API # 05-077-09240
Inspection # 696600093



Photo #4 Photo of site location where production equipment has been removed.