

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/21/2019

Submitted Date:

05/22/2019

Document Number:

689703139**FIELD INSPECTION FORM**

Loc ID 447695	Inspector Name: LONGWORTH, MIKE	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	Status Summary: <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input checked="" type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED
Operator Information: OGCC Operator Number: <u>10447</u> Name of Operator: <u>URSA OPERATING COMPANY LLC</u> Address: <u>950 17TH STREET, SUITE 1900</u> City: <u>DENVER</u> State: <u>CO</u> Zip: <u>80202</u>				Findings: <u>50</u> Number of Comments <u>1</u> Number of Corrective Actions <input checked="" type="checkbox"/> Corrective Action Response Requested ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:			
Contact Name	Phone	Email	Comment
Kellerby, Shaun		shaun.kellerby@state.co.us	
Knudson, Dwayne	970-456-3335	dknudson@ursaresources.com	All Inspections

Inspected Facilities:							
Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
447698	WELL	PR	01/09/2018	GW	045-23310	BMC B 12D-18-07-95	PR
447706	WELL	PR	03/24/2018	GW	045-23318	BMC B 23D-18-07-95	PR
447707	WELL	PR	03/27/2018	GW	045-23319	BMC B 14A-18-07-95	PR
447708	WELL	PR	02/02/2018	GW	045-23320	BMC B 23B-18-07-95	PR
447709	WELL	PR	03/28/2018	GW	045-23321	BMC B 23A-18-07-95	PR
447710	WELL	PR	03/01/2018	GW	045-23322	BMC B 13B-18-07-95	PR
447711	WELL	PR	02/08/2018	GW	045-23323	BMC B 13C-18-07-95	PR
447712	WELL	PR	02/22/2018	GW	045-23324	BMC B 23C-18-07-95	PR
447713	WELL	PR	02/23/2018	GW	045-23325	BMC B 13D-18-07-95	PR
447715	WELL	PR	01/19/2018	GW	045-23327	BMC B 13A-18-07-95	PR
447716	WELL	PR	01/14/2018	GW	045-23328	BMC B 22D-18-07-95	PR
449469	WELL	PR	12/10/2017	GW	045-23477	BMC B 32B-13-07-96	PR
449470	WELL	PR	11/29/2017	GW	045-23478	BMC B 42A-13-07-96	PR
449474	WELL	PR	11/23/2017	GW	045-23479	BMC B 41C-13-07-96	PR
449475	WELL	PR	12/30/2017	GW	045-23480	BMC B 42C-13-07-96	PR
449478	WELL	PR	02/10/2018	GW	045-23481	BMC B 43B-13-07-96	PR
449479	WELL	PR	11/27/2017	GW	045-23482	BMC B 32A-13-07-96	PR
449480	WELL	PR	04/04/2018	GW	045-23483	BMC B 43A-13-07-96	PR
449482	WELL	PR	01/07/2018	GW	045-23484	BMC B 42D-13-07-96	PR
449484	WELL	PR	12/21/2017	GW	045-23485	BMC B 32C-13-07-96	PR

449485	WELL	PR	02/28/2018	GW	045-23486	BMC B 43C-13-07-96	PR
449487	WELL	PR	12/22/2017	GW	045-23487	BMC B 42B-13-07-96	PR
449489	WELL	PR	11/28/2017	GW	045-23488	BMC B 41B-13-07-96	PR
449490	WELL	PR	11/28/2017	GW	045-23489	BMC B 41D-13-07-96	PR

General Comment:COGCC Inspection Report Summary

On Tuesday 05/21/2019 at approximately 1030 hours, I, Inspector Mike Longworth, conducted a inspection and sound reading based on Noise complainant 200447214 at Ursa Operating Company LLC BMC B Pad, at Location # 447695 in Garfield County, Colorado. While there, I observed transport trucks loading from the tank battery. Sound reading conducted during loading of transport. Reading was over a period of 1 hour and 5 minutes. Average dB level of 64.4 from distance of 192 ft and calculated 350 ft dB level of 59.18.

Noise complainant Doc # 200447214

Garfield County - Community Development was contacted spoke with Lindsay Krol on Wednesday 05/22/2019 at approximately 10:00am

During this inspection the following possible compliance issues were observed:

COGCC noise survey results indicate noise levels exceed limits in Rule 802. b. Oil and gas operations at any well site, production facility, or gas facility shall comply with the following maximum permissible noise levels.

ZONE Residential/Agricultural/Rural

7:00 am to next 7:00 pm 55 db(A)

7:00 pm to next 7:00 am 50 db(A)

See attached BMC B Pad 5/21/19 Sound Report and Inspection 68970319 photos.

C.A. Comply with Rule 802. Identify and install control measures.

C.A. Date 05/23/2019

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

Location Construction

Location ID: 447695 CDP: _____

Comment: _____

Corrective Action: _____

Date: _____

Form 2A COAs:

Comment: _____

Corrective Action: _____

Date: _____

Wildlife BMPs:

Comment: _____

Corrective Action: _____

Date: _____

Comment: _____

Corrective
Action: _____

Date: _____

On Site Inspection (305):

Surface Owner Contact Information:

Name: _____

Address: _____

Phone Number: _____

Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____

Phone Number: _____

Date Onsite Request Received: _____

Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Inspected Facilities				
Facility ID:	447698	Type:	WELL	API Number: 045-23310 Status: PR Insp. Status: PR
Producing Well				
Comment:	Producing well			
Corrective Action:		Date:		
Complaint				
Comment:	Noise complainant Doc # 200447214 Garfield County - Community Development was contacted spoke with Lindsay Krol on Wednesday 05/22/2019 at approximately 10:00am COGCC noise survey results indicate noise levels exceed limits in Rule 802. b. Oil and gas operations at any well site, production facility, or gas facility shall comply with the following maximum permissible noise levels. ZONE Residential/Agricultural/Rural 7:00 am to next 7:00 pm 55 db(A) 7:00 pm to next 7:00 am 50 db(A) See attached BMC B Pad 5/21/19 Sound Report and Inspection 68970319 photos.			
Corrective Action:	Comply with Rule 802. Identify and install control measures.		Date:	06/07/2019
Facility ID:	447706	Type:	WELL	API Number: 045-23318 Status: PR Insp. Status: PR
Producing Well				
Comment:	Producing well			
Corrective Action:		Date:		
Complaint				
Comment:	Noise complainant Doc # 200447214			
Corrective Action:		Date:		
Facility ID:	447707	Type:	WELL	API Number: 045-23319 Status: PR Insp. Status: PR
Producing Well				
Comment:	Producing well			
Corrective Action:		Date:		
Complaint				
Comment:	Noise complainant Doc # 200447214			
Corrective Action:		Date:		
Facility ID:	447708	Type:	WELL	API Number: 045-23320 Status: PR Insp. Status: PR
Producing Well				
Comment:	Producing well			
Corrective Action:		Date:		
Complaint				
Comment:	Noise complainant Doc # 200447214			
Corrective Action:		Date:		
Facility ID:	447709	Type:	WELL	API Number: 045-23321 Status: PR Insp. Status: PR
Producing Well				
Comment:	Producing well			
Corrective Action:		Date:		
Complaint				
Comment:	Noise complainant Doc # 200447214			
Corrective Action:		Date:		

<u>Producing Well</u>				
Comment:	Producing well			
Corrective Action:			Date:	
<u>Complaint</u>				
Comment:	Noise complainant Doc # 200447214			
Corrective Action:			Date:	
Facility ID: 447710 Type: WELL API Number: 045-23322 Status: PR Insp. Status: PR				
<u>Producing Well</u>				
Comment:	Producing well			
Corrective Action:			Date:	
<u>Complaint</u>				
Comment:	Noise complainant Doc # 200447214			
Corrective Action:			Date:	
Facility ID: 447711 Type: WELL API Number: 045-23323 Status: PR Insp. Status: PR				
<u>Producing Well</u>				
Comment:	Producing well			
Corrective Action:			Date:	
<u>Complaint</u>				
Comment:	Noise complainant Doc # 200447214			
Corrective Action:			Date:	
Facility ID: 447712 Type: WELL API Number: 045-23324 Status: PR Insp. Status: PR				
<u>Producing Well</u>				
Comment:	Producing well			
Corrective Action:			Date:	
<u>Complaint</u>				
Comment:	Noise complainant Doc # 200447214			
Corrective Action:			Date:	
Facility ID: 447713 Type: WELL API Number: 045-23325 Status: PR Insp. Status: PR				
<u>Producing Well</u>				
Comment:	Producing well			
Corrective Action:			Date:	
<u>Complaint</u>				
Comment:	Noise complainant Doc # 200447214			
Corrective Action:			Date:	
Facility ID: 447715 Type: WELL API Number: 045-23327 Status: PR Insp. Status: PR				

<u>Producing Well</u>				
Comment:	Producing well			
Corrective Action:			Date:	
<u>Complaint</u>				
Comment:	Noise complainant Doc # 200447214			
Corrective Action:			Date:	
Facility ID: 447716 Type: WELL API Number: 045-23328 Status: PR Insp. Status: PR				
<u>Producing Well</u>				
Comment:	Producing well			
Corrective Action:			Date:	
<u>Complaint</u>				
Comment:	Noise complainant Doc # 200447214			
Corrective Action:			Date:	
Facility ID: 449469 Type: WELL API Number: 045-23477 Status: PR Insp. Status: PR				
<u>Producing Well</u>				
Comment:	Producing well			
Corrective Action:			Date:	
<u>Complaint</u>				
Comment:	Noise complainant Doc # 200447214			
Corrective Action:			Date:	
Facility ID: 449470 Type: WELL API Number: 045-23478 Status: PR Insp. Status: PR				
<u>Producing Well</u>				
Comment:	Producing well			
Corrective Action:			Date:	
<u>Complaint</u>				
Comment:	Noise complainant Doc # 200447214			
Corrective Action:			Date:	
Facility ID: 449474 Type: WELL API Number: 045-23479 Status: PR Insp. Status: PR				
<u>Producing Well</u>				
Comment:	Producing well			
Corrective Action:			Date:	
<u>Complaint</u>				
Comment:	Noise complainant Doc # 200447214			
Corrective Action:			Date:	
Facility ID: 449475 Type: WELL API Number: 045-23480 Status: PR Insp. Status: PR				

<u>Producing Well</u>				
Comment:	Producing well			
Corrective Action:			Date:	
<u>Complaint</u>				
Comment:	Noise complainant Doc # 200447214			
Corrective Action:			Date:	
Facility ID: 449478 Type: WELL API Number: 045-23481 Status: PR Insp. Status: PR				
<u>Producing Well</u>				
Comment:	Producing well			
Corrective Action:			Date:	
<u>Complaint</u>				
Comment:	Noise complainant Doc # 200447214			
Corrective Action:			Date:	
Facility ID: 449479 Type: WELL API Number: 045-23482 Status: PR Insp. Status: PR				
<u>Producing Well</u>				
Comment:	Producing well			
Corrective Action:			Date:	
<u>Complaint</u>				
Comment:	Noise complainant Doc # 200447214			
Corrective Action:			Date:	
Facility ID: 449480 Type: WELL API Number: 045-23483 Status: PR Insp. Status: PR				
<u>Producing Well</u>				
Comment:	Producing well			
Corrective Action:			Date:	
<u>Complaint</u>				
Comment:	Noise complainant Doc # 200447214			
Corrective Action:			Date:	
Facility ID: 449482 Type: WELL API Number: 045-23484 Status: PR Insp. Status: PR				
<u>Producing Well</u>				
Comment:	Producing well			
Corrective Action:			Date:	
<u>Complaint</u>				
Comment:	Noise complainant Doc # 200447214			
Corrective Action:			Date:	
Facility ID: 449484 Type: WELL API Number: 045-23485 Status: PR Insp. Status: PR				

<u>Producing Well</u>			
Comment:	Producing well		
Corrective Action:		Date:	
<u>Complaint</u>			
Comment:	Noise complainant Doc # 200447214		
Corrective Action:		Date:	
<u>Facility ID: 449485 Type: WELL API Number: 045-23486 Status: PR Insp. Status: PR</u>			
<u>Producing Well</u>			
Comment:	Producing well		
Corrective Action:		Date:	
<u>Complaint</u>			
Comment:	Noise complainant Doc # 200447214		
Corrective Action:		Date:	
<u>Facility ID: 449487 Type: WELL API Number: 045-23487 Status: PR Insp. Status: PR</u>			
<u>Producing Well</u>			
Comment:	Producing well		
Corrective Action:		Date:	
<u>Complaint</u>			
Comment:	Noise complainant Doc # 200447214		
Corrective Action:		Date:	
<u>Facility ID: 449489 Type: WELL API Number: 045-23488 Status: PR Insp. Status: PR</u>			
<u>Producing Well</u>			
Comment:	Producing well		
Corrective Action:		Date:	
<u>Complaint</u>			
Comment:	Noise complainant Doc # 200447214		
Corrective Action:		Date:	
<u>Facility ID: 449490 Type: WELL API Number: 045-23489 Status: PR Insp. Status: PR</u>			
<u>Producing Well</u>			
Comment:	Producing well		
Corrective Action:		Date:	
<u>Complaint</u>			
Comment:	Noise complainant Doc # 200447214		
Corrective Action:		Date:	

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402053563	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4830448
689703140	BMC B Pad 5/21/19 Sound Report	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4830440
689703141	Inspection 68970319 photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4830441