

Kirby Eidson 28-4
API: 05-103-08974
Inspection: 679704407



Photo 1. Location.

Kirby Eidson 28-4
API: 05-103-08974
Inspection: 679704407



Photo 2. Landslide off edge of location.

Kirby Eidson 28-4
API: 05-103-08974
Inspection: 679704407



Photo 3. West side of location sliding off.

Kirby Eidson 28-4
API: 05-103-08974
Inspection: 679704407



Photo 4. Close up of hillside sliding.

Kirby Eidson 28-4
API: 05-103-08974
Inspection: 679704407



Photo 5. Location & landslide from ~2019 satellite image.

Kirby Eidson 28-4
API: 05-103-08974
Inspection: 679704407



Photo 6. Location & landslide from 2013 satellite image

Kirby Eidson 28-4
API: 05-103-08974
Inspection: 679704407



Photo 7. Location & landslide from 2009 satellite image

Kirby Eidson 28-4
API: 05-103-08974
Inspection: 679704407




Photo 8. Location & landslide from 1990's satellite image

Kirby Eidson 28-4
API: 05-103-08974
Inspection: 679704407



Photo 9. Blowdown tank floating in secondary containment.



Photo 10. Wellhead without sign.