

Inspection Photos
Location Name: Hillman 9-1 Location ID 417783
Inspection Date: 6/6/2019



Photo 1 – Location Sign



Photo 2 – Area of removed partially buried produced water vessels.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Location Name: Hillman 9-1 Location ID 417783
Inspection Date: 6/6/2019



Photo 3 – Crude Oil Steel AST



Photo 4 – Portable tank

