

Inspection Photos
Location Name: Schrandt 23-12
Location ID: 332431



Photo 1 – Wellhead

Photo 2 – Tank Battery

Inspection Photos
Location Name: Schrandt 23-12
Location ID: 332431



Photo 3 – Old Methanol Tank/Pump from previous inspection Doc ID 679600308

Photo 4 – Tank has been removed