

**Inspection Photos**  
**Location Name: Hotchkiss Federal #20-12D**  
**Spill/Release Point ID #464354**



**Spill/Release Point ID #464354. Gathering lines exposed in open excavation during this inspection.**



**Gathering lines from Hotchkiss Federal #20-12D. Produced water gathering line is the closest pipe.**

**Inspection Photos**  
**Location Name: Hotchkiss Federal #20-12D**  
**Spill/Release Point ID #464354**



**Soil stockpile from excavation of gathering lines.**



**View uphill of excavated area. Produced water gathering line is on the left in this photo.**

**Inspection Photos**  
**Location Name: Hotchkiss Federal #20-12D**  
**Spill/Release Point ID #464354**



**Wattles along south and west edges of stockpiled material.**



**Location of sample collected by COGCC staff on 6/6/19, adjacent to yellow ribbon within spill flow path.**

**Inspection Photos**  
**Location Name: Hotchkiss Federal #20-12D**  
**Spill/Release Point ID #464354**



**Proximity of sample location in relation to Spill/Release Point.**



**Ground cover vegetation within flow path.**

**Inspection Photos**  
**Location Name: Hotchkiss Federal #20-12D**  
**Spill/Release Point ID #464354**



**Similar vegetation adjacent to flow path of release.**



**Location of sample ID #0606191530 showing stressed vegetation in background.**

**Inspection Photos**  
**Location Name: Hotchkiss Federal #20-12D**  
**Spill/Release Point ID #464354**



**Stressed vegetation within flow path of release.**



**Condition of vegetation adjacent to flow path.**