

Inspection Photos

Location Name: NORTHRUP-67N57W /14SENW

Location #: 327106



Colorado Oil & Gas Conservation Commission
40.57546, -103.72699, 1402.0m, 36°
2018/08/29 02:02:38 PM

Photo #1

Northrup 1-14 (05-123-14168) Wellsite

Shut-In | SI

Weeds

Bradenhead NOT plumbed to surface

from prior insp.



Colorado Oil & Gas Conservation Commission
40.57543, -103.72701, 1394.0m, 312°
06/10/2019 01:40:02 PM

Photo #2

Northrup 1-14 Wellsite

Shut-In | SI

Weeds

Bradenhead NOT plumbed to surface



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: NORTHRUP-67N57W /14SENW

Location #: 327106



Colorado Oil & Gas Conservation Commission
40.57567, -103.72673, 1405.0m, 209°
2018/08/29 01:58:29 PM

Photo #3

Northrup 1-14, 2-14, Chinook #1 Location

Shut-down

Weeds

from prior insp.



Colorado Oil & Gas Conservation Commission
40.5757, -103.72668, 1399.0m, 205°
06/10/2019 01:36:27 PM

Photo #4

Northrup 1-14, 2-14, Chinook #1 Location

Shut-down

Weeds

Inspection Photos
Location Name: NORTHRUP-67N57W /14SENW
Location #: 327106



Photo #5
Northrup 1-14, 2-14, Chinook #1 Tank Battery
Shut-down
Weeds
from prior insp.



Photo #6
Northrup 1-14, 2-14, Chinook #1 Tank Battery
Shut-down
Weeds

Inspection Photos

Location Name: NORTHRUP-67N57W /14SENW

Location #: 327106



Photo #7

Northrup 1-14, 2-14, Chinook #1 Pit Area

Shut-down

Weeds

from prior insp.



Photo #8

Northrup 1-14, 2-14, Chinook #1 Pit Area

Shut-down

Weeds

Inspection Photos
Location Name: NORTHRUP-67N57W /14SENW
Location #: 327106



Photo #9
Northrup 1-14 Unused Equipment
Unused volume pot
from prior insp.



Photo #10
Northrup 1-14 Unused Equipment
Unused volume pot

Inspection Photos

Location Name: NORTHRUP-67N57W /14SENW

Location #: 327106



Photo #11

Northrup 1-14, 2-14 Separator stack

No Bird protection on stack

from prior insp.



Photo #12

Northrup 1-14, 2-14 Separator stack

No Bird protection on stack



Inspection Photos

Location Name: NORTHRUP-67N57W /14SENW

Location #: 327106



Photo #13

Northrup 1-14, 2-14 Separator stack

No Bird protection on stack

Up view

from prior insp.



Photo #14

Northrup 1-14, 2-14 Separator stack

No Bird protection on stack

Up view



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources