

Inspection Photos
API#045-09501
Operator: Caerus
Insp#692401085
Inspection Date: 5/31/2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

May 31, 2019

Inspection Photos: Caerus PA Benzel
Disposal API#045-09501



Photo#1:
Overview of Location and establishing vegetation.

May 31, 2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Caerus PA Benzel Disposal API#045-09501



Photo#2:
Reclaimed road with spotty revegetation.

May 31, 2019



Photo#3:
Reclaimed road with spotty revegetation



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Caerus PA Benzel Disposal API#045-09501



Photo#4:
Area in Location bare of vegetation ; soils
starting to wash.

May 31, 2019



Photo#5:
Area in Location with heavy establishment
of Kochia.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Caerus PA Benzel Disposal API#045-09501