

Laramie Energy LLC
API # 05-077-09012
Inspection # 696600110



Photo #1 Photo from entrance of location.

Laramie Energy LLC
API # 05-077-09012
Inspection # 696600110



Photo #2 Photo from entrance of location

Laramie Energy LLC
API # 05-077-09012
Inspection # 696600110



Photo #3 Well heads and signs on location.

Photo #4 Photo taken of tank battery

Laramie Energy LLC
API # 05-077-09012
Inspection # 696600110



Photo #5 photo of BMP that needs maintenance. Berm has erosion or has been pushed over edge all around location

Photo #6 photo of BMP that needs maintenance. . Berm has erosion or has been pushed over edge

Laramie Energy LLC
API # 05-077-09012
Inspection # 696600110



Photo #7 Signs and plywood on ground at entrance to location