

Inspection Photos

Location Name: Nile Waterflood Sanden Ehn Tank Batery

Location ID: 319646



Pic 1 unused equipment



Pic 2 unused equipment

Inspection Photos
Location Name: Nile Waterflood Sanden Ehn Tank Battery
Location ID: 319646



Pic 3 unused equipment



Pic 4 unused equipment

Inspection Photos
Location Name: Nile Waterflood Sanden Ehn Tank Battery
Location ID: 319646



Pic 5 unused equipment

Pic 6 unused equipment

Inspection Photos
Location Name: Nile Waterflood Sanden Ehn Tank Batery
Location ID: 319646



Pic 7 unused equipment



Pic 8 unused equipment

Inspection Photos

Location Name: Nile Waterflood Sanden Ehn Tank Batory

Location ID: 319646



Pic 9 unused equipment



Pic 10



Inspection Photos

Location Name: Nile Waterflood Sanden Ehn Tank Batery

Location ID: 319646



Pic 11



Pic 12 stained soil/possible leak

Inspection Photos

Location Name: Nile Waterflood Sanden Ehn Tank Batery

Location ID: 319646



Pic 13 stained soil/possible leak



Pic 14 pump house

Inspection Photos

Location Name: Nile Waterflood Sanden Ehn Tank Batery

Location ID: 319646



Pic 15



Pic 16 unused equipment in tank house/oily waste

Inspection Photos
Location Name: Nile Waterflood Sanden Ehn Tank Batory
Location ID: 319646



Pic 17