

# Inspection Photos

06/10/2019

Operator: CRUMLEY\* JACK - 21750

Location ID: 403355

Washington County, CO

Aaron Trujillo

NE Reclamation Specialist

COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos  
Operator Name: CRUMLEY\* JACK - 21750  
Location ID: 403355



**Photo 1:** Photo taken from well location, facing west. Photo an area approximately 35' at its longest, and 10' at its widest, where vegetation does not appear to be establishing. Additional reclamation will likely be needed to facilitate crop establishment over the well location.



**Photo 2:** Photo taken from well location, facing west. Photo shows inspector was only able to easily penetrate the top few inches of soil on the location. Compaction concerns may exist.

Inspection Photos  
Operator Name: CRUMLEY\* JACK - 21750  
Location ID: 403355



**Photo 3:** Photo shows inspector dug a compaction test pit. Photo shows possible compaction zone.



**Photo 4:** Photo taken from well location, facing north. Photo shows utility lines that end at the well location. Inspector confirmed with Impetrol Resources LLC that lines travel underground to the Ruth Walker 1, to the south