

Inspection Photos

06/10/2019

Operator: ADKINS OIL CO # 650

Location ID: 393754

Morgan County, CO

Aaron Trujillo

NE Reclamation Specialist

COGCC

Inspection Photos
Operator Name: ADKINS OIL CO # 650
Location ID: 393754



Photo 1: Photo taken from the southeast end of the location, facing west. Photos 1-2 provide an overview of the location.

Inspection Photos
Operator Name: ADKINS OIL CO # 650
Location ID: 393754



Photo 2: Photo taken from the southeast end of the location, facing north. Photos 1-2 provide an overview of the location.

Inspection Photos
Operator Name: ADKINS OIL CO # 650
Location ID: 393754



Photo 3: Photo taken from the east end of the location, facing west. Vegetation observed towards the central area of the location is predominantly undesirable weedy plant species. Little desirable vegetative establishment evident within these areas. Interseeding may be needed to facilitate reclamation.

Inspection Photos
Operator Name: ADKINS OIL CO # 650
Location ID: 393754



Photo 4: Photo taken from the access road. Photo shows areas where previous seeding was conducted has been re-disturbed. Surface owner appears to be utilizing access road.

Inspection Photos
Operator Name: ADKINS OIL CO # 650
Location ID: 393754



Photo 5: Photo taken from the access road. Photo shows areas where previous seeding was conducted has been re-disturbed. Surface owner appears to be utilizing access road.