

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/11/2019

Submitted Date:

06/11/2019

Document Number:

680305028**FIELD INSPECTION FORM**

Loc ID 336870 Inspector Name: SCHURE, KYM On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 66190Name of Operator: OMIMEX PETROLEUM INCAddress: 7950 JOHN T WHITE ROADCity: FORT WORTH State: TX Zip: 76120**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:8 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email | Comment |
|----------------|--------------|-------------------------------|---------|
| Fisher, Jeremy | 970-854-4733 | Jeremy_Fisher@omimexgroup.com | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|-------------------------|-------------|
| 280170 | WELL | PR | 03/15/2006 | GW | 125-09517 | BENNETT STATE 1-16-5-45 | PR |

General Comment:

Routine Site Inspection - FIR

Location

| | | | |
|--------------------|--|-------|--|
| Lease Road: | | | |
| Type | Access | | |
| comment: | Two track irrigated cropland - seasonal access | | |
| Corrective ActionL | | Date: | |

Overall Good: ☐

| | | | |
|----------------------|--------------|-------|--|
| Signs/Marker: | | | |
| Type | WELLHEAD | | |
| Comment: | Satisfactory | | |
| Corrective Action: | | Date: | |

| | | | |
|---------------------------|--------------|-------|--|
| Emergency Contact Number: | | | |
| Comment: | Satisfactory | | |
| Corrective Action: | | Date: | |

Overall Good: ☐

| | | | | | |
|----------------|------|--------|--|--|--|
| Spills: | | | | | |
| Type | Area | Volume | | | |

In Containment: No

Comment:

☐ Multiple Spills and Releases?

| | | | |
|--------------------|-------------|-------|--|
| Fencing/: | | | |
| Type | PUMP JACK | | |
| Comment: | Steel panel | | |
| Corrective Action: | | Date: | |

| | | | |
|--------------------------|----------------|-------|-----------------|
| Equipment: | | | corrective date |
| Type: Pump Jack | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Prime Mover | # 1 | | |
| Comment: | Electric motor | | |
| Corrective Action: | | Date: | |
| Type: Gas Meter Run | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Vertical Separator | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

| | | | |
|-----------------|--|--|--|
| Venting: | | | |
| Yes/No | | | |
| Comment: | | | |

| | | | |
|--------------------|--|-------|--|
| Corrective Action: | | Date: | |
| Flaring: | | | |
| Type | | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

| | | | |
|--|--|--|--|
| | | | |
|--|--|--|--|

| | | | | |
|-----------------------------|------------|-----------------------|------------|------------------|
| Inspected Facilities | | | | |
| Facility ID: 280170 | Type: WELL | API Number: 125-09517 | Status: PR | Insp. Status: PR |
| Producing Well | | | | |
| Comment: | GW | | | |
| Corrective Action: | | | | Date: |

| | | | | |
|--|--|--|--|--|
| | | | | |
|--|--|--|--|--|

Reclamation - Storm Water - Pit

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Gravel | In Process | Other | In Process | | | |

Comment: Located within irrigated cropland w/rotational tillage

Corrective Action:

Date:

Pits: ☐ NO SURFACE INDICATION OF PIT