

Inspection Photos
Location Name: Hankins #1
Location ID: 318634



Photo 1 TNK BTRY



Photo 2 Pig launcher.

Inspection Photos
Location Name: Hankins #1
Location ID: 318634



Photo 3 Unused flow lines have been marked



Photo 4 Sepco Meter house Berms repaired

Inspection Photos
Location Name: Hankins #1
Location ID: 318634



Photo 5 produced water tank berms have been repaired



Photo 6 Produced water tank plate installed of opening

Inspection Photos
Location Name: Hankins #1
Location ID: 318634




Photo 7 stained soil inside sep appears to have been removed



Photo 8 WH