

**FORM
INSP**Rev
X/15

State of Colorado Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

06/11/2019

Submitted Date:

06/11/2019

Document Number:

690003635

FIELD INSPECTION FORM
 Loc ID 329063 Inspector Name: Carlile, Craig On-Site Inspection ☐ 2A Doc Num:
Operator Information:

OGCC Operator Number: 47120

Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP

Address: P O BOX 173779

City: DENVER State: CO Zip: 80217-

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:

3 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**
Contact Information:

Contact Name	Phone	Email	Comment
, Inspections		COGCCinspections@Anadarko.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
249012	WELL	PR	03/01/2019	GW	123-16814	LORENZ L FEDERAL 30-12	PR

General Comment:

LocationOverall Good: ☒

Emergency Contact Number:

Comment: Corrective Action: Date: Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

Type	WELLHEAD		
Comment:			
Corrective Action:			Date:

Equipment:

Type: Plunger Lift	#		corrective date
Comment:			
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
			CENTRALIZED BATTERY		40.196370,-104.824650	
Comment:						
Corrective Action:					Date:	

Paint

Condition		
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:			Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 249012 Type: WELL API Number: 123-16814 Status: PR Insp. Status: PR**Producing Well**Comment: PR

Corrective Action:

Date:

COGCC Comments

Comment	User	Date
On Tuesday, June 11, 2019 at 11:01, I, Craig Carlile conducted an on-site inspection at: 329063, LORENZ-63N66W 30NWSW Operated by: Anadarko While there I observed: Producing well Weather: Skies clear, winds calm, temp 71 F Possible compliance issues observed: None This is a summary of the inspection report.	carlilec	06/11/2019

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
690003636	Photo	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4846300