

Location

Overall Good:

Signs/Marker:

| | | | |
|--------------------|----------------------|-------|--|
| Type | WELLHEAD | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type | TANK LABELS/PLACARDS | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type | BATTERY | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

| Type | Area | Volume | | |
|------|------|--------|--|--|
| | | | | |

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

| | | | |
|--------------------|--------------|-------|--|
| Type | WELLHEAD | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type | SEPARATOR | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type | TANK BATTERY | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Equipment:

| | | | |
|-----------------------------------|-----|-------|-----------------|
| Type: Bird Protectors | # 1 | | corrective date |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Plunger Lift | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Horizontal Heated Separator | # 1 | | |

| | | | |
|---------------------|-----|-------|--|
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Gas Meter Run | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Tanks and Berms:

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|--------------------|---|----------|-----------|---------|-----------------------|
| CRUDE OIL | 1 | 400 BBLs | STEEL AST | | 40.187490,-104.741580 |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |

Paint

| | |
|------------------|--|
| Condition | |
| Other (Content) | |
| Other (Capacity) | |
| Other (Type) | |

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|----------|---------------------|---------------------|-------------|
| Earth | Adequate | Walls Sufficient | Base Sufficient | Adequate |
| Comment: | | | | |
| Corrective Action: | | | | Date: |

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|--------------------|---|----------|--------------|---------|--------|
| PRODUCED WATER | 1 | OTHER | PBV CONCRETE | | |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |

Paint

| | |
|------------------|--------|
| Condition | |
| Other (Content) | |
| Other (Capacity) | 30 bbl |
| Other (Type) | |

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|-----------------------------|---------------------|---------------------|-------------|
| | | | | |
| Comment: | Shared with crude oil tank. | | | |
| Corrective Action: | | | | Date: |

Venting:

| | | | |
|--------------------|----|--|-------|
| Yes/No | NO | | |
| Comment: | | | |
| Corrective Action: | | | Date: |

Flaring:

| | |
|------|--|
| Type | |
|------|--|

| | |
|--------------------|-------|
| Comment: | |
| Corrective Action: | Date: |

Inspected Facilities

Facility ID: 245306 Type: WELL API Number: 123-13101 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment:

Corrective Action: Date: _____

COGCC Comments

| Comment | User | Date |
|---|----------|------------|
| <p>On Tuesday, June 11, 2019 at 12:13, I, Craig Carlile conducted an on-site inspection at: 323485, IONE UPRR-63N66W 35NWNE Operated by: Anadarko While there I observed: Well shut in and associated battery Weather: Skies clear, winds calm, temp 80 F Possible compliance issues observed: None This is a summary of the inspection report.</p> | carlilec | 06/11/2019 |

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|-------------|---|
| 690003646 | Photos | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4846305 |