

Construction and Stormwater Inspection

June 4, 2019

Operator: EXTRACTION OIL & GAS INC - #10459

Location ID: 456769

Inspection Document #: 697500193

Broomfield County, CO

NWNW Section 9 T1S R68W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: NORTHWEST A PAD
Location ID: 456769



Photo 1. Photo taken from the southwestern perimeter of the location on 5/24/19, facing West. A berm BMP has been installed around the perimeter of the location but it has not been installed with good engineering practices. The berm BMP has not been stabilized. Note: Other disturbances in the foreground are not associated with oil and gas operations.



Photo 2. Photo taken from the southwestern perimeter of the location on 6/4/19, facing East. Operator has started major construction activities (i.e., storing topsoil) prior to properly installing the perimeter BMP. Appears the Operator has not made any improvements to the BMPs since the previous inspection.

Inspection Photos
Location Name: NORTHWEST A PAD
Location ID: 456769



Photo 3. Photo taken from the western perimeter of the location on 6/4/19, facing South. See comments under Photo 2.

Inspection Photos
Location Name: NORTHWEST A PAD
Location ID: 456769



Photo 4. Photo taken from the southern perimeter of the location on 6/4/19, facing West. See comments under Photo 2.