

Inspection Photos
Loc#335329
Operator: Caerus
Insp#692401084
Inspection Date: 5/31/2019





Photo#1:
Overview of Location to Northwest.

May 31, 2019




COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Caerus Kell Loc#335329



Photo#2:
Subsidence in Interim areas.



Photo#3:
Subsidence in Interim areas.

May 31, 2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Caerus Kell Loc#335329